

From: Executive Director
Sent: Thursday, June 11, 2009 5:13 PM
To: +All HQ Employees
Subject: Building Update - June 11, 2009

There was a water event on the 10th floor today. A plumbing leak on the northwest corner of the 10th floor had previously been reported to DGS. Following the most recent DGS investigation, a drip pan was placed above the ceiling tile. Today, the pan overflowed and broke through the ceiling tile. It is estimated that approximately three gallons of water leaked to the floor. No one was injured. DGS has been called to investigate further. HTI also investigated and found no evidence of mold growth. DGS reports the leak has now been repaired, and the area is being dried.

We will pass along any new information as it becomes available.

Please continue to report any and all water leaks through the Building Assessment webpage.